

Miscellaneous Services

Parts Not Included

Ref. Code	Description	List Price	ECi Price
Camshafts - Recondition and Certify			
MS1	4 Cylinder	168.00	100.80
MS2	6 Cylinder	216.00	129.60
MS3	8 Cylinder	312.00	187.20
Connecting Rods			
MS4	Inspect and Check Alignment, Install Bushings (plus cost of Bushings)	36.72	22.03
MS5	Large Eng Repair - Plain Rods	60.00	36.00
MS6	Large Eng Repair - Tongue and Groove	140.00	84.00
Balance Set of Rods			
MS7	4 Cylinder	120.00	72.00
MS8	6 Cylinder	180.00	108.00
MS9	8 Cylinder	240.00	144.00
MS18	Convert 520 Conn Rod to 550 Conn Rod (ea.)	160.00	96.00
SI 1359 CAP Mod for 74644 Bolt, LW 12186 Nut			
MS10	Retag with New P/N 74502	40.00	24.00
Rocker Arms - Rebuilt			
MS11	Continental	28.56	17.14
MS12	Lycoming	28.56	17.14
MS13	Modify per TCM SBM 93-7 - Cut Groove only	32.00	19.20
MS14	Modify per TCM SBM 93-7 - Install Annulus Bushing (includes Bushing)	58.00	34.80
MS15	Modify per TCM SBM 77-2 - Drill Hole in Exhaust Rocker Arm	18.00	10.80
Valve Lifter Bodies			
MS16	Rebuild According to FAA Approval	28.00	16.80
—	Hourly Rate — For items billed hourly (minimum hourly rate is one-half (1/2) hour)	114.00 /Hr.	68.40 /Hr.
Inspection and Handling Charge			
Components which are deemed to be non-repairable by ECi standards will be subject to the following handling and inspection charges:			
SX1	Camshafts		15.00
SX2	Crankcase		55.00
SX3	Crankshaft		35.00
SX4	Cylinder		20.00