

<b>Miscellaneous Services</b>			
Parts Not Included			
Ref. Code	Description	List	Dealer Net
<b>Prop Strike Inspection</b>			
<b>Crankshaft - Clean, MPI, check runouts, measure &amp; polish journals, change gear dowl, replace counterweight bushings</b>			
CSPS4	4 Cylinder	330.00	198.00
CSPS6	6 Cylinder	462.00	277.20
CSPS8	8 Cylinder	594.00	356.40
<b>Crankcase - Clean, dye check, measure bores and check alignment</b>			
CCPS4	4 Cylinder	726.00	435.60
CCPS6	6 Cylinder	957.00	574.20
CCPS8	8 Cylinder	1,089.00	653.40
<b>Camshafts - Recondition and Certify</b>			
MS1	4 Cylinder	220.00	132.00
MS2	6 Cylinder	260.00	156.00
MS3	8 Cylinder	374.40	224.64
<b>Connecting Rods</b>			
MS4	Inspect and Check Alignment, Install Bushings (plus cost of Bushings)	46.20	27.72
MS5	Large Eng Repair - Plain Rods	72.60	43.56
MS6	Large Eng Repair - Tongue and Groove	158.40	95.04
<b>Balance Set of Rods</b>			
MS7	4 Cylinder	132.00	79.20
MS8	6 Cylinder	196.80	118.08
MS9	8 Cylinder	262.40	157.44
MS18	<b>Convert 520 Conn Rod to 550 Conn Rod (ea.)</b>	171.60	102.96
MS10	<b>SI 1359 CAP Mod for 74644 Bolt, LW 12186 Nut</b> Retag with New P/N 74502	52.80	31.68
<b>Rocker Arms - Rebuilt</b>			
MS11	Continental	32.80	19.68
MS12	Lycoming	32.80	19.68
MS13	Modify per TCM SBM 93-7 - Cut Groove only	39.60	23.76
MS14	Modify per TCM SBM 93-7- Install Annulus Bushing (includes Bushing)	66.00	39.60
MS15	Modify per TCM SBM 77-2 - Drill Hole in Exhaust Rocker Arm	26.20	15.72
<b>Valve Lifter Bodies</b>			
MS16	Rebuild According to FAA Approval	39.60	23.76
<b>Hourly Rate, Repair Service</b>			
ACOTH	Accessory Case Repair. Minimum rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
CCOTH	Crankcase Repair. Minimum hourly rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
CMOTH	Camshaft Repair. Minimum hourly rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
CROTH	Connecting Rod Repair. Minimum rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
CSOTH	Crankshaft Repair. Minimum hourly rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
CWOTH	Counterweight Repair. Minimum hourly rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
CYL23	Cylinder Repair. Minimum hourly rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
GOZOTH	Gozinta Repair. Minimum hourly rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
OSOTH	Oil Sump Repair. Minimum hourly rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
RAOTH	Rocker Arm Repair. Minimum hourly rate is one-half (1/2) hour.	132.00 /Hr.	79.20 /Hr.
<b>Inspection and Handling Charge</b>			
Components which are deemed to be non-repairable by ECi standards will be subject to the following handling and inspection charges:			
SX1	Camshaft	30.00	18.00
SX2	Crankcase	110.00	66.00
SX3	Crankshaft	70.00	42.00
SX4	Cylinder	20.00	20.00